

A1-26 Box contents:

Box 1 (red label on top of box)

- Stabilized PSU x1 (Farnell)
- Cylindrical metal mount x1
- Metal support w/ 3 cylindrical connectors x1
- Bag of connectors x1
- Invert jnc boxes x5
- Mains plug x2
- Plastic cups x6 (contain 7 plastic ^{syringe} covers)
- Epoxy resin x1
- Power plug adapters (3 Swiss, 3 EU)
- Syringe x1
- Duct tape x1
- Thorlabs source imp x1
- Extension lead x1 (UK)
- Allen keys set x1
- Grey connectors in a zip lock bag x15
- Black plastic spacers & BNC connector x5
- Bag of M5 & M3 screws
- Metal struts with screws (3 long, 3 medium, 3 short)
- C-shaped clamps with screws x3
- Metal washers (?) with blue top x6
- Sample strut x1

Box 1 continued

Small screwdriver x1

Long strut made of 5 connectors x1

Support struts with black c-shaped clamps x1

Bag with 2 screw threads, 1 Thorlabs black cylinder

2 5 washers

Variety of black Thorlabs mounts (see photo)

Pulser x1

Flat cables box

6 colorful cables

1 gray cable

1 long gray hose

Rectangular metal support with oval hole ~~x1~~ x2

Solder x1

Aluminium brick x1

Black circle with BNC connector x1

Metal FACOM dial x1

LEMO ~~connectors~~ cables x2

LEMO to some connector (black, see photos) x1

Cooknell pre-amp x1

SHV cable x1

~~BNC~~ short BNC + T-piece x1

BNC power supply x1 (big gray)

Spirit level x1

Gray board with black connectors (see photos) x1

Box 1 continued

Big blue G-clamps x 10

Small G-clamps x 5

L-shaped metal clamps with screws x 4

NIM Quad Bias x 1

NIM BNC PSU x 1

NIM Ortec amplifier x 1